




Large Air Cooled Generator Failure

Henry Tarnecky
AVP - Sr. Engineering Specialist, FM Global
2017 IRIS Rotating Machinery Conference

FM Global Basics

- Commercial/Industrial Property Insurer
- Mutual Co., founded in 1835 in USA
- 5,300 employees including 1,800 engineers
- Global – 66 offices serving clients in ~150 countries
- Clients – large organizations, 30% Fortune 1000

Zachariah Allen – Founder



Textile manufacturer, scientist, lawyer, writer, inventor and civil leader

FM Global Basics




FM Global Difference

- “The Majority of Loss is Preventable”
- Mutual with Specialty Focus
- Engineering Services
- Global Product Delivery
- Outstanding Claims Service
- Strong Client Partnerships
- Business Risk Consulting

Loss Prevention Resources

- Dedicated Client Service Team
- Data Sheets
- Specialist Loss Prevention Engineers
- Subject Matter Experts & Industrial Principle Engineers
- Research
- Training (on site, corporate)
- Approval



SOURCE: FM Global loss data, 2011–2015

Outline - This Presentation

- Generator Failure Case Study
- FM Global Loss Prevention Strategy for Generators

Case Study-Generator Failure

■ Site Information

- 600 MW - 2x1 Combined Cycle Plant – (2) CT's & (1) Stm Turbine
- Cycled 7am to 11pm Monday thru Friday
- Commissioned in 2005
- Can operate 1X1 or bypass Stm Turbine @ reduced load

Case Study-Generator Failure


■ The Unit

- 255 MW, 21 kV - 2 pole, air cooled, 60HZ
- Steam turbine driven
- Satisfactory acceptance testing @ commissioning
- Manufactured in 2005
- 15,000 hours (625 days) of operation at the time of the incident with no significant previous issues

Case Study-Generator Failure

- Unit trips offline suddenly – reportedly differential relay trip (modern digital multi relay package installed)
- Condition assessed by operators and restart attempted three more times – relay tripped each time
- Turbine/Generator secured for damage investigation
- All vital parties notified (Management, OEM, Insurance etc.)

Severe arc fault damage top bar #4 at phase lead connection



Case Study-Generator Failure


- Damage assessment:
- Stator arc fault damage to “B” phase top bar # 4 insulation noting cracked phase connection (exciter end) flashed over to ‘C’ phase
- Operator restart attempts caused more severe arc fault damage and end winding physical movement after the initial fault
- Resulted in retaining ring, rotor forging & field coil overheating & metal loss damage



11 o'clock position where initial arc flash over occurred



Other as found blocking & phase lead connection exciter end



Phase lead blocking - note poor taping and displaced wedge.


- Found 4 of 6 phase lead connections cracked in the strand braze area where loose or no blocking evident
- Phase lead connections with secure blocking were not cracked
- Long term insulation vibration wear at failed bar # 4 noted
- Bump test found signs of 120 HZ resonance present in end winding suggesting “High Cycle Fatigue”
- Suspect rotor/field & retaining ring arc fault damage (removed for off site evaluation - repair)




“Phase lead connection crack”

(copper lug brazed to the bar end - then trapezoidal intermediate piece & circular phase ring)

Stator - poor strand to phase lead braze connections






Retaining Ring Removed from Rotor at Repair Shop (exciter end)


Retaining Ring & Rotor damage assessment:

- The retaining ring on the exciter end sustained arcing damage at the taper end.
- Splatter debris was found throughout the rotor.
- Ground fault (arcing damage) at exciter end through the damper winding to ground on the face of the slot tooth between coils 1 and 2 & on the same coil on the exact opposite side.
- Arc damage was also found on inboard pole coil Nos. 1 and 2 and outboard pole @ coil No. 1.
- Arc damage was found on a tooth on the forging.

Retaining ring inside surfaces



Severe arc fault metal loss & overheating damage – ring required replacement becoming long lead time item



Rotor coil and forging arc fault damage (exciter end)

Rotor Repair – off site

- The rotor weighed approximately 130,000 lbs. and was considered a “super load”.
- Regulations about transporting a super load are strict requiring special permits and caused delays.
- Rotor became the critical path in terms of reassembling the generator. (4 months & 5 days later)
- Locating a replacement retaining ring was critical long lead item

Case Study-Generator Failure - Cause



- Root Cause - High Cycle Fatigue due to 120 HZ resonance - induced end turn vibration damage
- Contributing Cause - Inferior strand to phase lead braze connections created crack initiation point and accelerated damage time line to failure.




New phase lead connections
(H clip - more rugged design)



Original design



More robust end blocking design to reduce vibration



Case Study-Generator Failure

■ Lessons learned

– Validated benefit of


- Modal Analysis – “Bump Testing” phase lead connections & end winding during acceptance test

– Improvements:

- Phase lead braze connections improved
- End winding support blocking improved and eliminated 120 HZ resonance
- PD monitoring installed
- Continuous fiber optic end winding vibration monitoring installed (18 exciter end and 6 on drive end)

Generator Failures-Risk Factors

Environment
 Operating conditions
 Age/history
 Maintenance
 Operator training






Operator training, contingency plan, safety device

PM program

- Every generator is different
 - Design or Manufacturing Issues
 - Operating History
 - Base Load vs. Peaking
 - New versus Old
 - Etc...

Recent trend

Condition Based Approach vs Rotor Out Inspection



View of core damage taken with MAGIC robot

PM program

- FM Global recommends the following as appropriate:
 - Establish generator electrical testing frequency as well as test scope
 - Install on-line condition monitoring systems and consider robotic inspections
 - Closely manage findings (rate of degradation)
 - If test results or trends indicate high risk - plan remedial action & repairs before an in service failure.

PM program

Stator Winding and Core Test	Rotor inspection & test	On-line monitoring
Insulation resistance & polarization index	Insulation resistance/Polarization index(PI)	Partial discharge/EMI
Power factor	Impedance testing/RSO testing/open circuit test	Flux probe
Partial Discharge (power factor tip-up)	DC conductivity	Core monitor/RTD
Core loop test (EL-CID)	Visual inspection	End winding vibration
Semi-conductive coating resistance	NDE on rotor forging and fan	Hydrogen dew point monitor
Wedge tightness	NDE retaining ring	Shaft voltage/current
DC conductivity		
Capacitance mapping (water-cooled unit)		
Pressure/Vacuum decay test(water-cooled unit)		

Generator Failures

FM Global
Property Loss Prevention Data Sheets

5-12

May 2010
Interim Revision January 2016
Page 1 of 29

ELECTRIC AC GENERATORS

Table of Contents

	Page
1.0 SCOPE	2
1.1 Changes	2
2.0 LOSS PREVENTION RECOMMENDATIONS	2
2.1 Protection	2
2.2 Equipment and Process Protection	2
2.3 Operation and Maintenance	6
2.3.1 In-Service	6
2.3.2 Condition Monitoring	6
2.3.3 Generator Dismantle Intervals	7
2.3.4 Visual Inspection	7
2.3.5 Testing	7
2.3.6 Overvoltage (hipot) testing	9
3.0 SUPPORT FOR RECOMMENDATIONS	10
3.1 Visual Indications	10
3.2 Generator Tests	11
3.3 Failure Modes and Abnormal Operating Conditions	15
3.3.1 Core	15
3.3.2 Stator	16
3.3.3 Rotor	19
3.3.4 Mechanical Hazards	20
3.3.5 Abnormal Electrical Conditions	21
3.4 Stator ground fault protection	24
3.5 Condition Monitoring	24
3.6 Loss History	26
3.6.1 Loss History with Utility AC Generators	26
3.6.2 Loss History with Industrial AC Generators	26
4.0 REFERENCES	27
4.1 FM Global	27
4.2 Other	27
APPENDIX A GLOSSARY OF TERMS	27
APPENDIX B DOCUMENT REVISION HISTORY	29
APPENDIX C BIBLIOGRAPHY	29

List of Figures

Fig.1 Typical Unit Generator-Transformer Configuration. (Courtesy of IEEE Power Engineering Society) . 3

List of Tables

Table 1. Recommended Protective and Alarm Devices for AC Generators 5

FM Global
Property Loss Prevention Data Sheets

5-3
13-2

April 2012
Page 1 of 28

HYDROELECTRIC POWER PLANTS

Table of Contents

	Page
1.0 SCOPE	2
1.1 Changes	2
2.0 LOSS PREVENTION RECOMMENDATIONS	2
2.1 Electrical	2
2.2 Operation and Maintenance	2
2.2.1 Electrical	2
2.2.2 Mechanical	4
2.3 Equipment and Processes	4
2.4 Protection	5
3.0 SUPPORT FOR RECOMMENDATIONS	6
3.1 Loss History	6
4.0 REFERENCES	7
4.1 FM Global	7
4.2 Others	7
APPENDIX A GLOSSARY OF TERMS	7
APPENDIX B DOCUMENT REVISION HISTORY	7
APPENDIX C SUPPLEMENTARY INFORMATION	8
C.1 Description	8
C.2 Generator Protection	23
C.2.1 Generator Fire Detection Testing	26
C.2.2 Generator Fire Hazards	26
C.3 Maintenance	27
APPENDIX D NFPA STANDARDS	28


List of Figures

Fig. 1. Arrangement of major components of typical hydroelectric generating station.	8
Fig. 2. Francis turbine and generator. (Allis Chalmers, Hydro-Turbine Division)	10
Fig. 3. Open flume setting.	11
Fig. 4. Plan view of six-jet vertical impulse turbine.	12
Fig. 5. Kaplan turbine and generator. (Allis Chalmers, Hydro-Turbine Division)	13
Fig. 6. Axial-flow turbine-runner on horizontal shaft.	14
Fig. 7. Axial-flow turbine-runner on inclined shaft.	14
Fig. 8. Bulb-type hydraulic turbine and generator. (Allis Chalmers, Hydro-Turbine Division)	15
Fig. 9. Sectional elevation of diagonal-flow (Danaz) turbine.	16
Fig. 10. Pumped-storage arrangement.	16
Fig. 11. Reversible pump/turbine-generator unit.	18
Fig. 12. Schematic diagram of governor.	21
Fig. 13. Permanent magnet generator. (Woodward Governor Co.)	22
Fig. 14. Protective devices for synchronous hydroelectric generator.	24
Fig. 15. Recommended protective devices for induction hydroelectric generators.	25

List of Tables

Table 1. Recommended Protection Devices for Alternating-Current Generators	3
Table 2. Analysis of Failures in Hydro-Turbines and Generators, 1971 through 1980	7
Table 3. Resistance to Pitting of Different Runner Materials	20

Electrical Protection: The Defense Line



■ FM Global focus

- Adequate Relay Protection
(ANSI / IEEE C 37.102)
- Operational As A System
(RELAYS, DC BATTERIES, CONTROL WIRING etc.)
- Operator Response/Training

Conclusion

- **FM Global Loss Prevention Strategy for Generators**
 - Verify Adequate Electrical Protection
 - Emphasize Operating Training
 - Promote Condition Based PM - online monitoring (PD, End winding vibration, flux probe etc.)

FM Global Data Sheet

5-12: Electrical AC Generators

5-19: Switchgear and Circuit Breakers

5-20: Electrical Testing

5-3: Hydro Power Station

7-79: Fire Protection for Gas Turbine and Electric Generators

7-101: Fire Protection for Steam Turbines and Electric Generators