

The background of the entire page is a detailed technical drawing or blueprint, rendered in a light blue color. It features various mechanical components, lines, and text, typical of an engineering drawing. The drawing is partially obscured by a large blue and black rectangular area in the center, which contains the company name and product title.

SOHRE TURBOMACHINERY®

SHAFT-RIDING BRUSHES

128 MAIN STREET • P. O. BOX 1099 • MONSON, MASSACHUSETTS 01057-1099 • U. S. A.
PHONE 413-267-0590 or 800-207-2195 • FAX 413-267-0592 or 413-267-0590

PRESENTATION OUTLINE

1. Overview

- » ***Impact of shaft current***
- » ***Causes of shaft current***
- » ***What can be done about shaft currents?***
- » ***Measurements and Importance of baseline data***

2. Sources of shaft currents

3. Sohre Brushes

- » ***Why Sohre Brushes***
- » ***General guidelines***
- » ***Brush models and typical installations***

4. Brush Maintenance


- » ***Alignment***
- » ***Insulation testing***

5. Voltage/current measurement and monitoring


IMPACT OF SHAFT CURRENT/VOLTAGE

- ***SPARK EROSION:***
 - ***THRUST AND JOURNAL BEARING DAMAGE***
 - ***DAMAGED GEARS AND SEALS***
- ***INCORRECT INSTRUMENTATION READINGS***
- ***SHAFT CURRENT PROBLEMS CAN BE DIFFICULT TO DETECT WHEN MACHINE IS NOT IN OPERATION***


FROSTED THRUST BEARING




FROSTED THRUST BEARING 2



MAGNIFIED FROSTING




BEARING SPARK TRACKS




MAGNIFIED SPARK TRACKS




COUPLING FACE – HIGH CURRENT DAMAGE



FROSTED SHAFT




ROLLER ELEMENT DAMAGE



D10011

TURBINE ROTOR WHICH BECAME MAGNETIZED BY RUBS. MAGNETIC FIELD WAS STRONG ENOUGH TO HANG NAILS AND A SMALL MIRROR FROM THE ROTOR.

MAGNETIZED ROTOR



NAIL

POCKET MIRROR

SOURCES OF SHAFT CURRENT


- ***STATIC DISCHARGE***
 - ***Caused by flow of charged particles***
 - ***Turbines, compressors, pumps***
 - ***Random high voltage short duration spikes***
 - ***Typically low energy***
 - ***Can be intermittent and dependent on process conditions***

SOURCES OF SHAFT CURRENT

- ***GENERATORS***
 - *Field imbalance*
 - *Ground faults*
 - *Static exciter filter issues*
- ***MOTORS***
 - *Variable frequency drives*

SOURCES OF SHAFT CURRENT

- **MAGNETIZED ROTORS**
 - *Homopolar generator effect*



SOURCES OF SHAFT CURRENT

- ***HOW DO ROTORS GET MAGNETIZED***
 - ***Electrical currents through the machine***
 - ***Welding and Self-Excitation***
 - ***Impact***
 - ***Manufacturing processes***

MEASURING SHAFT VOLTAGE


- ***MEASURING SHAFT VOLTAGE***
 - *Shaft voltage is Noise*
 - *Oscilloscope is the ONLY effective tool*
- ***SOMETIMES DIFFICULT TO DO***
 - *Difficult Environment – Hot and Noisy*
 - *Oscilloscopes require practice to use effectively*
 - *Low Voltage High Current*
 - *High Voltage Short Duration*

MEASURING SHAFT VOLTAGE



Peak approx. 0.6 V - Measurement taken with 20x probe – 0.2 V/div

GROUNDING SHAFT STATIC DISCHARGE




Peak approx. 2 V - Measurement taken with 200x probe – 1 V/div

UNGROUNDING SHAFT STATIC DISCHARGE



Peak approx. 100 V - Measurement taken with 200x probe – 40 V/div

HIGH FREQUENCIES DAMPING / ATTENUATION NEEDED



Peak approx. 1.4 V - Measurement taken with 5x probe – 0.5 V/div

GROUNDING BRUSHES

- ***CARBON/GRAPHITE BRUSHES***
 - *Most common grounding brush material*
 - *Carbon has a sweet spot*
 - *Carbon needs moisture to conduct electricity*
 - *Carbon has a current density sweet spot*
- ***COPPER STRAPS***
 - *Copper has low resistance*
 - *Copper straps are inexpensive*
 - *Copper oxides can impact the resistance to ground and can be abrasive*
 - *Copper oxide formation is related to current density*

SOHRE GROUNDING BRUSHES



- **GOLD / SILVER COMPOSITE**
 - *Expensive*
 - *Low and consistent conductivity*
 - *Low maintenance requirements*
- **ISOLATED PATH TO GROUND**
 - *Reduced inductive feedback*
 - *Effective accurate measurement of shaft voltage*

ADDRESSING SHAFT CURRENT ISSUES

- ***ACCEPT THE PROBLEM AND DEAL WITH IT***
 - ***Certain processes and machines produce static discharge***
 - ***Change operating parameters, if possible***
 - ***Size grounding brush accordingly***
 - » ***Brush depletion rate is a power function***
- ***DEMAGNETIZE PARTS***
 - ***The process of reducing the magnetic field is called Degaussing***
 - ***The magnetic field cannot be completely removed***
 - ***The residual magnetic field can increase in intensity without adequate grounding***