

---

# Experience with Stator Insulation Testing & Turn/Phase Insulation Failures in the Power Generation Industry

May 7, 2018

**Heedong Kim, Taesik Kong**

Korea Electric Power Company  
Research Institute, Daejon, Korea

**Sang Bin Lee**

Korea University, Seoul, Korea

# Objectives

---

- ▶ **Summary of KEPCO's 17+ yrs. experience on stator insulation testing for mains-fed, MV AC motors**
  - Predictive maintenance program & statistics on test records (99'~)
  - Analysis of 15 cases of turn/phase insulation failures (11'~)
- ▶ **Provide insight on turn/phase insulation failures**



# Stator Insulation Failures

---

- ▶ **Leading cause of forced motor outages in power plants [1]**
  - Complete loss or reduction in power generation capability
  - 83.6% groundwall (GW) insulation, 16.4% turn insulation failure
  - Most commercial tests intended for GW insulation testing
- ▶ **Significant reduction in GW insulation failures w/ predictive maintenance (PM) program**




**GW insulation failure, 6.6 kV, 550 kW**

# Insulation PM Testing (KEPCO)

---

- ▶ **PM program setup in 1999**
- ▶ **Tests performed**
  - Insulation resistance (IR), polarization index (PI)
  - Delta leakage current ( $\Delta I_{leak}$ ), delta  $\tan\delta$  ( $\Delta \tan\delta$ )
  - Off-line partial discharge (PD)
- ▶ **Test period**
  - 5 years (< 10 yrs. of service); 3 years (> 10 yrs. of service)
  - 1 year (insulation in poor condition)
- ▶ **Recommendations**
  - 1) Cleaning/drying; 2) Refurbishment; 3) Stator rewind

# Testing & Maintenance Procedure





# Summary of KEPCO Insulation Testing

- ▶ # of test records for type of power plant (1999-2016)

Type of power plant	# of power plants	# of generating units	# of MV motors tested	# of tests performed
Thermal	19	98	3,119	8,152
Combined cycle	9	30	362	695
Pumped storage	5	12	48	69
Nuclear	4	15	1,231	2,938
Total	37	155	4,760	11,854

- Stator tests at nuclear plants excluded (performed at MCC)

- ▶ # of alarms for each test for type of power plant

Type of power plant	# of tests performed	IR	PI	$\Delta I_{leak}$	$\Delta \tan \delta$	PDIV	$Q_{m,100}$	$Q_{m,125}$
Thermal	8,152	61	565	1,063	828	245	127	207
Combined cycle	695	2	43	24	22	10	8	19
Pumped storage	69	0	5	0	0	0	0	1
Total	8,916	63	713	1,087	830	255	135	227

# Summary of KEPCO Insulation Testing

- ▶ # of motors with 1, 2, 3 failure alarms produced with each type of test & # of refurbishment & rewind recommendations

Type of power plant	# of tests performed	1 failed test	2 failed tests	3 failed tests	Insulation refurbishment	Stator rewind
Thermal	8,152	499	793	30	47	110
Combined cycle	695	31	19	2	4	13
Pumped storage	69	1	0	0	0	0
Total	8,916	531	812	32	51	123


- Active repair recommendations made for 174 of 8,916 motors (1.95%) with high risk of GW insulation failure
  - Significant reduction in GW insulation failures since 1999
  - **Most recent insulation failures in turn or phase insulation**
  - GW failures still present when recommended testing cycle or repair actions are not followed (production or budget restraints)

# Turn Insulation Failures

## ▶ Root causes - combination of:

- Long term thermal & mechanical aging
- Deficiency in turn insulation design or manufacturing
- PD deterioration at turn-GW insulation interface ( $> 4$  KV) [12]-[13]

→ Loss of elec./mech. strength: **Puncture due to short rise-time voltage surge or mechanical shock**



## ▶ Typical fault location

- **Terminal end coil:** high electrical stress & turn voltage stress
- **Endwinding (EW) slot exit:** bent portion w/ manufacturing & operating stresses



# Turn Insulation Failures

## ▶ Consequences

- Induction of high amplitude circulating fault current in shorted loop
  - Localized heating: melted copper & damage over wide area
  - GW insulation failure (and/or stator core damage)
- Tripping of motor: forced outage



# Case Studies - Turn Insulation Failure

## ▶ 13 cases of turn insulation failure (2011-2016)

- Investigation based on direct observation (or dissection), reports, interviews from on-site maintenance team or repair shop
- Variance in amount of information available for each case

	Application	$V_{rated}$ (kV)	$P_{rated}$ (kW)	Poles	Yrs. of service	Situation at failure		Failure location			Turn insulation material	Stator core lamination damage
						Failure at startup/operation	Time to failure after last startup	EW/slot	Location	Coil # from Terminal		
M1	Condensate pump	6.6	310	4	3	Startup	0	EW	Slot exit	-	Glass fiber	None
M2	Condensate pump	6.6	310	4	5	Startup	0	EW	Slot exit	-	Glass fiber	None
M3	Condensate pump	6.6	350	4	7	Operation	24 hr	Slot	Mid-slot	-	Glass fiber	None
M4	Condensate pump	6.6	350	4	8	Startup	0	EW	Slot exit	>3	Glass fiber	None
M5	Boiler feed pump	6.6	2250	2	3	Startup	0	EW	Slot exit	1	Glass fiber	None
M6	Boiler feed pump	6.6	2250	2	4	Startup	0	EW	Slot exit	-	Glass fiber	None
M7	Induced draft fan	6.6	4300	8	5	Operation	3 mo.	Slot	Mid-slot	1	Glass fiber	None
M8	Induced draft fan	6.6	4300	8	8	Operation	12 hr.	Slot	Mid-slot	1	Glass fiber	None
M9	Transport blower	6.6	205	4	7	Startup	0	EW	Slot exit	2	Glass fiber	None
M10	Circulating pump	6.6	350	4	16	Startup	0	Slot	Mid-slot	-	Enamel	None
M11	Pulverizer	6.6	450	8	5	Operation	6 mo.	EW	-	-	Glass fiber	None
M12	Primary air fan	4.0	485	6	9	Operation	1 wk.	EW	Bend	>3	Mica	None
M13	Primary air fan	6.6	1678	4	15	Operation	10 mo.	EW	Slot exit	3	Glass fiber	None

# Turn Insulation Failure - Observations

---

- ▶ No noticeable trend in correlation between turn failure & application, rated power, number of poles, years of service
- ▶ 7 of 13 failures occurred at motor startup
  - 6 of 7 failures located at EW slot exit (M1, M2, M4, M5, M6, M9)
  - 2 of 3 failures in 1<sup>st</sup> or 2<sup>nd</sup> coil (M5, M9)
  - Typical failures: fast risetime voltage surge & mechanical forces
- ▶ 6 of 13 failures occurred during operation >12 hrs after startup





# Endwinding Failures - Observations

- ▶ 9 of 13 failures in EW at or near slot exit – typical failures reported
  - Bending stresses present at manufacturing

	Application	$V_{rated}$ (kV)	$P_{rated}$ (kW)	Situation at failure		Failure location			Turn insulation material	Stator core lamination damage
				Failure at startup/operation	Time to failure after last startup	EW/slot	Location	Coil # from Terminal		
M1	Condensate pump	6.6	310	Startup	0	EW	Slot exit	-	Glass fiber	None
M2	Condensate pump	6.6	310	Startup	0	EW	Slot exit	-	Glass fiber	None
M3	Condensate pump	6.6	350	Operation	24 hr	Slot	Mid-slot	-	Glass fiber	None
M4	Condensate pump	6.6	350	Startup	0	EW	Slot exit	>3	Glass fiber	None
M5	Boiler feed pump	6.6	2250	Startup	0	EW	Slot exit	1	Glass fiber	None
M6	Boiler feed pump	6.6	2250	Startup	0	EW	Slot exit	-	Glass fiber	None
M7	Induced draft fan	6.6	4300	Operation	3 mo.	Slot	Mid-slot	1	Glass fiber	None
M8	Induced draft fan	6.6	4300	Operation	12 hr.	Slot	Mid-slot	1	Glass fiber	None
M9	Transport blower	6.6	205	Startup	0	EW	Slot exit	2	Glass fiber	None
M10	Circulating pump	6.6	350	Startup	0	Slot	Mid-slot	-	Enamel	None
M11	Pulverizer	6.6	450	Operation	6 mo.	EW	-	-	Glass fiber	None
M12	Primary air fan	4.0	485	Operation	1 wk.	EW	Bend	>3	Mica	None
M13	Primary air fan	6.6	1678	Operation	10 mo.	EW	Slot exit	3	Glass fiber	None

# Turn Insulation Failure - Observations





# Endwinding Failures - Observations

---


- ▶ Melted copper & burning over wide area observed for ALL cases
- ▶ Turn failure does not necessarily cause GW insulation failure
  - Turn fault can cause tripping of open phase, imbalance, phase current relays before GW failure
  - M12: no visual signs of GW current path + high IR value
  - Turn failures in the tip of EW common w/ crossover coil designs






# Endwinding Failures - Observations


- ▶ “Crossover” coils common in MV motors w/ low power ratings
- ▶ Multiple & neighboring turns placed in slot width in same layer [15]
- ▶ Bending of coils required in EW (near tip)
- ▶ Higher electrical & manufacturing (bending) stresses in turn insulation near EW tip (terminal end coil)



Straight-up coil



Crossover coil



# Slot Winding Failures - Observations

- ▶ 4 of 13 failures near center of slot

	Application	$V_{rated}$ (kV)	$P_{rated}$ (kW)	Situation at failure		Failure location			Turn insulation material	Stator core lamination damage
				Failure at startup/operation	Time to failure after last startup	EW/slot	Location	Coil # from Terminal		
M1	Condensate pump	6.6	310	Startup	0	EW	Slot exit	-	Glass fiber	None
M2	Condensate pump	6.6	310	Startup	0	EW	Slot exit	-	Glass fiber	None
M3	Condensate pump	6.6	350	Operation	24 hr	Slot	Mid-slot	-	Glass fiber	None
M4	Condensate pump	6.6	350	Startup	0	EW	Slot exit	>3	Glass fiber	None
M5	Boiler feed pump	6.6	2250	Startup	0	EW	Slot exit	1	Glass fiber	None
M6	Boiler feed pump	6.6	2250	Startup	0	EW	Slot exit	-	Glass fiber	None
M7	Induced draft fan	6.6	4300	Operation	3 mo.	Slot	Mid-slot	1	Glass fiber	None
M8	Induced draft fan	6.6	4300	Operation	12 hr.	Slot	Mid-slot	1	Glass fiber	None
M9	Transport blower	6.6	205	Startup	0	EW	Slot exit	2	Glass fiber	None
M10	Circulating pump	6.6	350	Startup	0	Slot	Mid-slot	-	Enamel	None
M11	Pulverizer	6.6	450	Operation	6 mo.	EW	-	-	Glass fiber	None
M12	Primary air fan	4.0	485	Operation	1 wk.	EW	Bend	>3	Mica	None
M13	Primary air fan	6.6	1678	Operation	10 mo.	EW	Slot exit	3	Glass fiber	None



# Slot Winding Failures - Observations

- ▶ 4 of 13 failures near center of slot
  - Clear signs of melted copper and ground current path






# Slot Winding Failures - Observations

---

- Clear signs of melted copper and ground current path



# Slot Winding Failures - Observations

---

- ▶ Core inter-laminar insulation failure not observed for any of the 13 cases
  - Visual inspection, core loop test performed during rewind
  - Relays act fast enough to prevent core damage even with large ground current with solid grounding in domestic power plants
  - Not all faults result in ground current through stator core
    - EW failure not close to core (M13, crossover coils)
    - Trip caused by asymmetry or open circuits
    - Ground current flow through core end plate





# Case Studies - Turn Insulation Material

- ▶ Strong correlation between failures & turn insulation material
  - Glass fiber: 11 cases; enamel: 1 case; mica-based: 1 case
  - % of glass fiber turn insulation **very high** considering that 50% of MV motors glass-fiber based & 50% mica-based in Korea

	Application	$V_{rated}$ (kV)	$P_{rated}$ (kW)	Poles	Yrs. of service	Situation at failure		Failure location			Turn insulation material
						Failure at startup/ operation	Time to failure after last startup	EW/ slot	Location	Coil # from Terminal	
M1	Condensate pump	6.6	310	4	3	Startup	0	EW	Slot exit	-	Glass fiber
M2	Condensate pump	6.6	310	4	5	Startup	0	EW	Slot exit	-	Glass fiber
M3	Condensate pump	6.6	350	4	7	Operation	24 hr	Slot	Mid-slot	-	Glass fiber
M4	Condensate pump	6.6	350	4	8	Startup	0	EW	Slot exit	>3	Glass fiber
M5	Boiler feed pump	6.6	2250	2	3	Startup	0	EW	Slot exit	1	Glass fiber
M6	Boiler feed pump	6.6	2250	2	4	Startup	0	EW	Slot exit	-	Glass fiber
M7	Induced draft fan	6.6	4300	8	5	Operation	3 mo.	Slot	Mid-slot	1	Glass fiber
M8	Induced draft fan	6.6	4300	8	8	Operation	12 hr.	Slot	Mid-slot	1	Glass fiber
M9	Transport blower	6.6	205	4	7	Startup	0	EW	Slot exit	2	Glass fiber
M10	Circulating pump	6.6	350	4	16	Startup	0	Slot	Mid-slot	-	Enamel
M11	Pulverizer	6.6	450	8	5	Operation	6 mo.	EW	-	-	Glass fiber
M12	Primary air fan	4.0	485	6	9	Operation	1 wk.	EW	Bend	>3	Mica
M13	Primary air fan	6.6	1678	4	15	Operation	10 mo.	EW	Slot exit	3	Glass fiber



# Case Studies – Turn Insulation Material

---

- ▶ Mica paper: most common above 6.6 kV
  - Resistant to PD
  - Superior thermal properties
- ▶ Enamel turn insulation not common above 3.3 kV
  - Organic & non-PD-resistant
- ▶ Glass fiber
  - High breakdown strength, resistant to PD & tracking
  - Organic polymers around round glass vulnerable to failure
- Motors with glass-fiber turn insulation have higher probability of failure
- Rewind w/ mica-paper recommended for failed motors

# Case Studies - Phase Insulation Failure

---

## ▶ 2 cases of phase insulation failures (2015-2016)


	Application	$V_{rated}$ (kV)	$P_{rated}$ (kW)	$P$	Yrs. of service	Status at failure	Failure location	Stator core lamination damage	Test records (mo. before failure)
M14	Boiler feed pump	6.6	3800	2	9	Operation	Lead cable	None	19, 53
M15	Boiler feed pump	6.6	4500	4	12	Operation	Lead cable-EW	None	56, 116

- Typically occur in lead cables or EW close to terminal end
- Typical root causes
  - Insufficient spacing conductors b/w different phases
  - Surface contamination
- Results in very high current flow and significant damage

# Phase Insulation Failure - Observations

---

- ▶ M14
  - Open phase failure due to phase insulation failure b/w lead cables
- ▶ M15
  - Significant damage due to insulation failure b/w lead cable & terminal end EW
- ▶ Cause of failure: surface leakage current & arcing due to insufficient spacing & coal dust contamination



# Impact of Insulation Failure

---

## ▶ **Cost of rewind**

- M1-M2, 310 kW condensate pump: 26,000 USD
- M7-M8, 4,300 kW induced draft fan: 130,000 USD

## ▶ **Forced outage of induced draft fan (M7-M8), primary air fan (M12-M13)**

- 50% reduction in generator power output
- Loss of profit for power plant with 50% reduction
  - 50% reduction in power generation (12 hrs.) for 500 MW generating unit
  - 150,000 USD ~ 600,000 USD (based on 2011-2016 system marginal price in Korea)

# Test Records of Failed Motors

- ▶ Voltage cannot be applied directly to turn/phase insulation with the 5 GW insulation tests for Y-connected MV motors w/ no access to neutral
- ▶ Insulation test records analyzed for motors that failed turn/phase insulation (identical motors also analyzed)

	Months before failure	IR (MΩ)	PI	PDIV (kV)	Q <sub>m,100</sub> (pC)	Q <sub>m,125</sub> (pC)	ΔI (%)	Δtanδ (%)	PD pattern
M1	1	59300	3.54	2.3	<b>28000</b>	<b>32000</b>	3.01	1.85	Internal
M2	28	67200	4.02	4.0	6200	8700	3.17	1.91	-
M2'	-	55900	3.45	2.3	7300	<b>12100</b>	3.46	2.08	Internal
M3	0.5	59600	5.81	2.8	3200	4900	2.29	1.55	-
M3'	-	29700	5.02	2.8	9100	17000	0.64	1.1	Internal
M4	0.25	24800	4.01	2.5	6000	8200	2.52	1.88	-
M4'	-	28200	5.33	2.6	3700	5800	2.51	1.92	-
M7	46	4800	2.33	2.6	8600	<b>12700</b>	4.19	2.55	Slot
M7	28	6240	4.91	2.2	7700	<b>16000</b>	4.23	2.52	Slot
M7'	-	1510	4.37	2.4	6000	<b>11000</b>	5.75	3.17	Slot
M8	57	1390	2.89	3.5	1400	2400	7.6	4.2	-
M8	0.5	6090	3.58	<b>1.9</b>	<b>19000</b>	<b>24000</b>	6.92	3.89	Internal
M8'	-	2640	3.06	<b>1.8</b>	<b>13000</b>	<b>20300</b>	6.3	3.5	Internal
M9	23	37800	2.51	2.1	7000	8000	8.02	2.03	-
M9'	-	38000	2.13	2.0	7000	7500	5.01	2.22	-
M9''	-	41500	2.20	1.9	7000	8500	5.42	2.54	-
M12	68	52200	6.23	2.2	1900	2300	0.62	0.05	-
M12	31	35200	2.81	2.9	1700	2600	0.09	0.12	-
M12	0.5	40100	6.43	2.8	1800	2900	0.19	0.13	-
M12'	-	17300	5.54	-	730	9300	0.02	0.1	-
M14	53	2350	9.62	3.4	3000	6500	0.66	0.5	-
M14	19	21400	4.12	2.9	6600	<b>25000</b>	0.72	0.69	Internal
M15	116	9520	8.48	3.4	1100	2200	1.96	1.48	-
M15	56	11900	5.55	2.5	5500	<b>11500</b>	1.91	1.3	Internal
M15'	-	1440	4.54	<b>1.7</b>	<b>50000</b>	<b>52000</b>	2.14	1.2	Internal

# Test Records of Failed Motors - Observations

---

- ▶ IR/PI tests are screening tests & do not indicate insulation degradation
  - ▶ Increasing trend or relatively higher value of  $\Delta \tan \delta$  or  $\Delta I_{leak}$  cannot be observed for failed motors
  - ▶ High level or increasing trend in PD activity could be observed for some motors prior to turn or phase insulation failure (M1, M7, M8, M14, M15)
  - ▶ PD activity for failed motors were much lower than that of motors with refurbishment / rewind recommendations (and even some identical motors that did not fail)
- **5 GW stator tests cannot be relied on for advanced warning of turn or phase insulation failures**



# Conclusions

---

- ▶ GW insulation failures have been significantly reduced since stator insulation PM program has been initiated – 1.95% of stators refurbished or rewound with high risk of GW failure
- ▶ Motors w/ glass-fiber turn insulation had higher risk of failure - 84.6% of failures (rewound with mica-based insulation)
- ▶ Insulation system design & manufacturing important factor – 4 pairs of motors with identical design have failed (8 of 13)
- ▶ Phase insulation failures due to insufficient spacing & contamination caused significant damage
- ▶ It is difficult to predict turn or phase insulation failures with IR, PI,  $\Delta \tan \delta$ ,  $\Delta I_{leak}$ , & PD tests

# Conclusions

---

- ▶ Turn or phase insulation failures do not necessarily cause GW insulation failure or GW current
- ▶ Core inter-laminar insulation failure was not observed in any of the 15 turn or phase insulation failures
- ▶ On-line PD monitoring may find phase insulation failure in advance, but not turn insulation failures
- ▶ Investigation of new concepts for turn or phase insulation condition assessment are in progress

# Acknowledgment

---

## ▶ **Motor repair shops**

- Chaewoong Lim, *SN Heavy Industry Co.*
- Shinyoung Park, *Hansung Heavy Industrial Co.*

## ▶ **Motor testing services**

- Daesung Yoon, *Korea Electrical Safety Services*

## ▶ **Power generation plants**

- Jaehyun Park, *Korea Midland Power Co.*
- Youngha Hwang, *Korea Western Power Co.*
- Byunggu Park, *Korea Southeast Power Co.*
- Youngman Kang, *Korea Southern Power Co.*
- Chan Namkoong, *Korea East-West Power Co.*

# References

---

1. P.F. Albrecht, J.C. Appiarius, R.M. McCoy, E.L. Owen, and D.K. Sharma, "Assessment of the reliability of motors in utility applications - updated," *IEEE Trans. Energy Convers.*, vol. EC-1, no. 1, pp. 39-46, Mar. 1986.
2. IEEE Std. 43-2013, IEEE Recommended Practice for Testing Insulation Resistance of Electric Machinery.
3. IEEE Std. 286-2000, IEEE Recommended Practice for Measurement of Power Factor Tip-Up of Electric Machinery Stator Coil Insulation.
4. IEEE Std. 1434-2014, IEEE Guide for the Measurement of Partial Discharges in AC Electric Machinery.
5. G.C. Stone, I. Culbert, E.A. Boulter, and H. Dhirani, *Electrical insulation for rotating machines – design, evaluation, aging, testing, and repair*, IEEE Press Series on Power Engineering, John Wiley and Sons, 2014.
6. IEEE Guide for Testing Turn Insulation of Form-Wound Stator Coils for Alternating-Current Electric Machines, IEEE STD 522, 2004.
7. D.E. Schump, "Testing to assure reliable operation of electric motors," *Proc. of IEEE IAS Annual Meeting*, vol. 2, pp. 1478-1483, Oct. 1990.
8. J. Wilson, "Current state of surge testing induction machines", *Proc. of Iris Rotating Machine Conference*, 2003.
9. E. Wiedenbrug, G. Frey, and J. Wilson, "Early intervention", *IEEE Ind. Appl. Mag.*, vol. 10, no. 5, pp. 34-40, 2004.
10. J.H. Dymond, M.K.W. Stranges, and N. Stranges, "The effect of surge testing on the voltage endurance life of stator coils," *IEEE Trans. Ind. Appl.*, vol. 41, no. 1, pp. 120-126, Jan./Feb. 2005.
11. O.M. Nassar, "The use of partial discharge and impulse voltage testing in the evaluation of interturn insulation failure of large motors," *IEEE Trans. Energy Convers.*, vol. EC-2, no. 4, pp. 615-621, Dec. 1987.
12. N.K. Ghai, "Design and application considerations for motors in steep-fronted surge environments," *IEEE Trans. Ind. Appl.*, vol. 33, no. 1, pp. 177-186, Jan./Feb. 1997.
13. G.C. Stone, B.K. Gupta, M. Kurtz, and D.K. Sharma, "Investigation of turn insulation failure mechanisms in large AC motors," *IEEE Trans. Power App. and Syst.*, vol. PAS-103, no. 9, pp. 2588-2593, Sept. 1984.
14. H. Kim, T. Kong, S.B. Lee, T.-J. Kang, N. Oh, Y. Kim, S. Park, G.C. Stone, "Experience with Stator Insulation Testing and Turn/Phase Insulation Failures in the Power Generation Industry," *IEEE Trans. Ind. Appl.*, vol. 54, no. 3, May/June 2018.
15. Michael Liwshitz-Garik, *Winding alternating-current machines: a book for winders, repairmen, and designers of electric machines*, Van Nostrand Technology & Engineering, 1950.