


# A 30 Years Reliability Survey of a Generator Family

---



**Relu ILIE**

**Iris Rotating Machine Conference**

June 24, 2021


# Purpose

---

- Reliability survey of 12 generators type 9H2 over about 30 years. Accumulated 350 unit-year represents a large statistical population
- The purpose is to preserve the history of this generator family, 10 units being sold as per Government's structural changes
- Generators driven by GE 9E-class gas turbines. More than 3000 frame 9E/7E units installed around the world in the last 40 years
- 50 Hz generators type 9H2 comparable to 60 Hz generators 7H2, but 7E units have 20% higher speeds, 9E have 40% higher outputs

# Features

- Hydrogen cooled generators 11.5 kV, almost identical in their design and dimensions
- Slightly different rating according to install year:
  - 6 rated 133.75 MVA (ANSI C50), 1989-1992
  - 4 rated 137.50 MVA (ANSI C50), 1993-1994
  - 2 rated 148.50 MVA (IEC 34), 1996
- Armature and field windings insulation class F designed for class B temperature rise
- ANSI C50.15 starting frequency 500 starts/year



# Hydrogen-Cooled Generator


HYDROGEN-COOLED GENERATOR NO. 335X938		RATING				
2 POLES	3 PHASE	Y CONN.	50 HERTZ	3000	RPM	GAS 98% PURITY
TOTAL TEMPERATURE AT RATING				KVA:	137500	
GUARANTEED NOT TO EXCEED:				ARMATURE AMPS:	8803	
100 °C ON ARMATURE BY DETECTOR				ARMATURE VOLTS:	11500	
110 °C ON FIELD BY RESISTANCE				FIELD AMPS:	1219	
MAXIMUM COLD GAS TEMPERATURE 40° C				EXCITATION VOLTS:	500	
INLET LIQUID: 37 °C MAX.				POWER FACTOR:	0.85	
CAUTION! BEFORE INSTALLING, OPERATING OR DISMANTLING, READ INST.						
GE Power Systems General Electric Company				Schenectady New York Made in U.S.A.		



# Operation

---


- Initially all 12 in open cycle. Later, 6 units integrated in 3-shaft combined cycle
- Initially all 12 burned distilled oil. Later, 8 units converted to natural gas
- Operated in two-shift: ~100 starts/year for open cycle, ~200 starts/year for CC
- Typical signs of negative-sequence event (unreported) found in one rotor
- A couple of seal-oil ingress incidents occurred, without direct consequences



# Maintenance

---

- Initially rotor-out outage performed during turbine major inspection acc. to O&M book
- Later on, maintenance updated according to OEM's documents and user's procedures
- Major outage at maximum 12 years intervals, exceptions for system / budgetary constraints
- Every generator passed during the years two rotor-out and several borescope inspections
- One unsuccessful robotic inspection attempt




# Rotor Issues

---

- **Creepage block migration**

- Blocked cooling vents induced thermal sensitivity and abnormal vibrations
- Appeared in 6 generators, as soon as after 1400-1800 starts or 10-13 years
- In severe cases of blocked cooling passages the solution was full rewind





# Rotor Issues

---

- **Terminal stud leaves**

- Cracked / broken copper leaves may lead to excitation circuit interruption
- Occurred in 4 generators, as soon as after 1100-1500 starts or 5-7 years
- Once tripped loss-of-field relay. Solution: replacing the stud (partial rewind)




# Rotor Issues

---

- **Dislocated turn insulation**

- In the end-winding, may lead to shorted turns and thermal sensitivity
- Found in several machines, for instance after 2200 starts and 11 years
- Can be only addressed during a partial or complete rewinding work






# Rotor Issues

---

- **Collector leads insulation**

- Damaged +/- insulation may lead to ground faults or be related to H<sub>2</sub> leaks
- 3 occurrences, e.g. after 2300 starts (12 years). Once tripped ground relay
- In some cases can be repaired in the field, in others rewind necessary




# Rotor Issues

---

- **Shorted turns or coils**

- May lead to thermal sensitivity and vibrations
- Shorted coils case after 1500 starts (15 years), following copper deformation
- Shorted turns case after 2500 starts (14 years) because damaged interturn insulation




# Rotor Issues

---

- **Pole crossover event**

- Broken pole-to-pole connector resulted in loss-of-field protection trip
- Occurred after 2800 starts and 14 years, because copper fatigue failure
- The solution was a complete rewind (following additional findings)





# Rotor Issues

---

- **Rotor rewind summary**

- During the years, 5 complete and 2 partial rewinds have been performed
- Most rewinds done in our power plants, with old copper and without high speed tests
- In other 3 cases, the faulty rotor replaced by spare and repaired in contractor's factory





# Stator Issues

---

- **Loose slot wedges**

- Most probably related to two-shift operation / vibrations / oil contamination
- Occurred in all machines, as soon as after 13-14 years or 1400-1500 starts
- Solution: partial or full replace of Camel Back wedges by Piggy Back (inclined plane) & top ripple springs





# Stator Issues

---

- **Greasing and loose ties**

- Greasing results from end-winding loose ties / blocks, oil contamination
- Found in some generators, for example after 18 years and 3300 starts
- All loose ties have been removed and replaced, or retighten / repaired







# Stator Issues

- **Stator rewedge summary**

- During the years, full rewedge was done in 6 machines
- Partial rewedge was performed in other 4 generators
- Rewedge extent according to wedge tightness test & acceptance criteria



# Other Issues

---

- **Bushing damages**
  - In 2 generators, after 13-17 years or just 1300 starts
- **Increased vibrations**
  - Occurred in 4 machines from various reasons:
  - One case related to thermal sensitivity (closed vents)
  - Another case was a result of misalignment condition
  - In other cases may be difficult to find the root cause
- **Static excitation**
  - Voltage regulators based on solid-state analogue electronic cards, original and still in operation






# Monitoring & Testing

---

- Visual / borescope inspection of stator and rotor, electrical tests: insulation resistance, PI
- Offline tan delta and PD up to phase voltage. At major outage also ELCID, wedge tightness, RSO
- Complete rewinds opportunity used to perform NDT metallurgic inspection on forging (TIL 1292)
- Flux probes installed in 9 out of 12 generators: 4 w/o shorts, 3 with 1 short, 2 with 2-4 shorts
- No online stator winding PD monitors installed. No special issues on stator insulation
- In some generators EMI done, without findings





# Critical Spare Parts



---

- **Stator spare parts**

- 6 top bars and 6 bottom bars (10% of installed) stored, luckily never used
- A complete set of wedges and ancillary materials stored for emergency

- **Spare rotor**

- Acquired in 2010, after interchangeability study by OEM. Used 3 times



# Conclusions

---

- 35 years after manufacturing, 25-31 service years and 2700-5400 starts, 9H2 generators are still reliable, mainly as a result of their design simplicity
- The most common failure modes are related to the two-shift operation mode. By EPRI 1008351 cycling regime may increase forced outages up to 5 times
- Most stators (10 out of 12) experienced during the years a partial / full rewedge, performed after an average operation life of 2600 starts or 16 years
- Most rotors (10 out of 12) underwent significant maintenance, a partial / full rewinding or a replacement, after an average 2400 starts or 14 years
- It is expected that a new series of rotor rewinds and stator rewedge will be necessary in the near future, despite the number of starts slightly decreased

---

**Thank you!**

**reluilie@iec.co.il**