Magnetic unbalance problem on 60 year old hydrogenator – analysis and solution

Jun 22nd 2021











Ozren Husnjak, Veski Ltd (Croatia)

www.veski.hr



History

- the plant was commissioned in 1957.
- two units, ~30 MW each (Francis)
- three-phase synchronous generator (10.5 kV, 36000 kVA)
- nominal rotational speed 300 rpm (20 pole unit, 50 Hz)
- suspended design (thrust bearing above the generator)
- both units had similar issues











History of a problem (problems)

Unit 1 vs Unit 2:

- both units had similar issues
- on Unit 1 increased vibrations after operation at run-away speed

Unbalances detected:

• mechanical (+ run-out)

presented at HydroVision

- electromagnetic (magnetic) large (~300 µm difference from mechanical)
- thermal

Additional issues:

- misaligned rotor and bearing axes
- loose connection between thrust collar and shaft

2016.





Measurement layout (typical)

- 18 channel portable instrument used
- typically relative and absolute vibrations measured
- 4 sensors per measurement plane
- additional measurements included air gap and magnetic flux Water measurements inlet

Potation

Х





Sensors used



below slip-rings, above thrust collar





turbine level



4 sensors per measurement plane (2x relative vibration, 2x absolute vibration)

Calculations performed (descriptors) / Vibrations

- Smax (obsolete as of 2018, when ISO 20816-5 was published)
- 1x, 2x, 3x rotational frequency harmonic(s) amplitudes and phases
- peak-to-peak, EqPeak, Rest, DC
- rotational speed
- RMS (for absolute vibrations)







Calculations performed (descriptors) / Air-gap





Year 2012. / Unit 1 / 1x harmonic

UGB (X, Y) / LGB (X, Y) / TGB (X, Y)





Year 2013. / Unit 1. / Dynamical rotor line prior to overhaul

Dynamical rotor line measurements just prior to the overhaul

- dynamical rotor line is, basically, rotor ODS at the 1x (which is dominant)
- multiple measurement planes (5)
- indicated on the figure

The dynamical rotor line indicates:

- there is no solid connection (shrink fit is lost) between thrust collar and shaft
- additional proof is out-of-phase movement when comparing vibrations above and below thrust collar



dynamical rotor line



Prior to and during the overhaul on Unit 1



Vibration caused damaged pads (used to set bearing clearance) on LGB

UGB clearance setup during the overhaul



Prior to and during the overhaul on Unit 1



Rotor lowering

Balancing weights below the generator (two-plane balancing performed)





Year – 2013. / After the overhaul prior to balancing



120.0

5, 110.0·

100.0-

90.0-

80.0-70.0· 60.0

50.0 40.0

30.0 20.0 10.0

19:50:00

19.50.25

19:50:50 19:51:15 19:51:40

27/07/2013 27/07/2013 27/07/2013 27/07/2013 27/07/2013 27/07/2013

19:52:05

19:52:30

19:52:55 19:53:20 19:53:45 19:54:10

27/07/2013 27/07/2013 27/07/2013 27/07/2013

19:54:35

UGB (X, Y) / LGB (X, Y) / TGB (X, Y)

- at LGB the vibrations increase due to electromagnetic and (later) thermal reasons
- similar changes (bet decreasing) visible at UGB vibrations

- zoomed in portion of the graph for mechanical ٠ rotation and excited state
- it is neccessary to balance the unit so that there are no more than 100 µm in all operating regimes
- (absolute vibration criteria was set to 0.5 mm/s)



LGB-X 🖊

LGB-Y

TGB-X

TGB-Y



Year – 2013. / after the overhaul and after the balancing



← 100 µm!

- thermal effect for relative vibrations after balancing



Although, a better approach would be to minimize electromagnetic unbalance!



Air-gap & Magnetic flux measurements to the rescue!



• balancing can only be done to reduce vibrations to certain extent



Rotor poles and excitation leads



Air-gap and Magnetic Flux sensors



Air-gap measurements / Unit 2



(data from unit 2 – larger electromagnetic unbalance)



Air-gap + Magnetic Flux measurements (unit 2)



(data from unit 2 – larger electromagnetic unbalance)



Overhaul suggestions / Suggestion 1 (better)

- equalize air gap by the poles (by re-wedging them)
- for Unit 2 this means move poles 2-11 closer to stator for 0.8 mm (slide)
- this would equalize by ±0.2 mm







Dovetail connection pole to rim





Overhaul suggestions / Suggestion 2

- if the pole re-wedging is not possible, regimes with extreme vibrations should be avoided
- if unit balancing is done in such a way as to minimize vibration amplitudes after the excitation is turned on (field flash) there will be large vibrations in mechanical rotation
- operation in mechanical rotation can be avoided (or reduced significantly) by turning on excitation automatically above 85% nominal speed regardless of the operating regime
- in this way large vibrations will be present only during run-up and run-downs for rotational speeds below 250 rpm
- these conditions are to be maintained in all operating regimes except when the generator protection system is turned on (for example, on stator short-circuits) but these events are rare



Load rejection from 20 MW / Unit 2







Load rejection from 30 MW / Unit 2



VESKı

20



Thank you for your attention!



