

IRMC 2024

Renaissance Las Vegas , NV

June 17-20, 2024

324 Generator Failure Discoveries, Concerns, & Repair

W. Howard Moudy
Director of Operations
National Electric Coil
hmoudy@national-electric-coil.com
724-787-4967
www.National-Electric-Coil.com




Background

- **The Facility is a 2 on 1 combined cycle plant**
 - Two Siemens Westinghouse 501F CT's with AEROPAC Generators.
 - One GE – D11 ST a 324 generator
- **The 324 Generator - 320,100 kVA; 18 kV; 3600 rpm**
- **Maintenance outage several months prior to failure**
 - Full stator rewedge followed by a DC HiPot
 - No lingering concerns
- **In Service Failure Event**
 - Ground Fault – T2 / T5
 - NEC selected to diagnose and propose repair options



NEC Mobilization

- Early expectation that known issues with the EE end winding and in specific phase straps were at the core of the failure.
- TE end winding discovery identified as likely problem or at least contributor
- Bump testing performed



Inspection



- Bulging and signs of overheating near core and at Series Connection
- Potential issue in series connection possible source of overheating?




Origin of Overheating?

- Connection stripped to investigate.
- No indications of heat generation from the brazed series connection
- Heat effected area indications inboard of the series connection




Origin of Overheating?

- Observation of overheating increased moving toward the core from the Series Connection
- Excavation of the bulge near the core
- Overheating evidence increased in proximity to the conductor stack




Origion of Overheating

- Slot 63 core wedges removed exposing top filler overheating indications.
- Lifting the top filler exposed signific signs of overheating on the top coil.
- Top coil indications extended approximately 4' into the slot from the turbine end with the worst indications between 10" to 18 " from the turbine end of the core.




Probable Origin of Overheating & Point Of Failure

- Most significant burning found **14” from the TE of the core in slot #63**



Isolation of Failed Coil #63




Top Coil Slot #63

Isolated from T2 – T5 Phase

- Good winding resistance (megger) testing results.
- Polarization Index (PI) - at 10 kV DC.
 - $PI = R_{10min}/R_{1min}$:
 - Phase A $PI = 21.7G\Omega/2.70G\Omega = 8.04$
 - Phase B $PI = 21.7G\Omega/3.57G\Omega = 6.09$
 - Phase C $PI = 15.6 G\Omega/3.03G\Omega = 5.16$
- A ramp test graded DC Hipot was performed on all three phases up to 37 kV DC with leakage measured at 37.0 kV DC:
 - A - 4.3 μ Amps
 - B - 5.0 μ Amps
 - C - 4.9 μ Amps.




Failed Coil #63 Removal





Side Ripple Filler Discovery

- Side Ripple Filler – Height
 - Significantly short
- Side Filler Material Preparation
 - Protruding corners, not rounded and/or oriented properly – “Birds Beaking”
 - Bar Abrasion



Coils Removed

- Failed Top Bar – Slot #63
- Three Adjacent Top Bars



NEC High Voltage Lab Investigation & Analysis

Failed Coil Arrival - Cracked Strand Discovery WHY?

- Cracks in shipment due to copper hydrogen embrittlement from extreme heat in the generator hydrogen atmosphere




Initial Considerations & Observations

- **No signs of electrical aging** of ground wall or the bar that could have contributed to the failure mechanism.
- Calculation of the failed bar operational voltage is 5.2 kV AC – EE, and 4.5kV AC – TE. The maximum electrical stress did not exceed 35 VPM. Therefore, **Corona activity was not a possible contributor**, given low electrical stress (voltage) and the pressurized hydrogen environment.
- Extreme overheating of the bar on the TE from the series connection to approximately 48” into the core.




Dissection & Analysis Plan

- Failed Bar #63 was carefully dissected into coupons
- Ground wall and strand insulation carefully analyzed.
 - Strand insulation was completely gone area of failure
 - Strand coupons harvested from non- heat effected area for analysis



Failure Root Cause

Representative sample of strand coupons harvested from non-heat affected areas of failed bar #63



Analysis Conclusions

Root Cause – Shorted Strands:

- Compromised strand insulation of top bar #63
- Compromised strand insulation progressively shorted to adjacent strands, creating severe overheating
- The severe overheating damaged the bar ground wall insulation from the inside adjacent to the shorted strands outward to the bar surface.
- Eventually, ground wall deterioration allowed the ground fault failure.



Actions To Support At Site Repair

Manufacture replacement bar for failed bar #63

- Improved strand insulation
- Maintain loss characteristics of original bar design
- Ensure bar geometry to match winding at site
 - Strip an adjacent bar to aid in mechanical verification of the new bar

Qualify stripped adjacent bar for re-insulation, and process along with the new bar

- Autoclave processed single coil VPI

Two remaining adjacent bars utilized to calibrate final mechanical verification



Stator Bar Shorted Strands

- Magnified Failed Strand

- Single serving Dacron glass
- Thin serving, no crosshatching
- Exposed conductor



- Magnified Replacement Strand

- Double serving Dacron glass
- Crosshatched – increased coverage
- No exposed conductor





Replacement Bar Manufacturing & Bar Reinsulation



- Replacement bar losses matched original design
- Reinsulated & replacement bar utilized qualified materials and processes
- All bars (replacement, reinsulated, and both adjacent) successfully completed 100% final factory electrical testing and mechanical verification



New Replacement Coil, Reinsulated Coil, & Cleaned Up Coils, Installed



Repairs Complete







Future Considerations & Concerns

- Strand insulation discovery brings into question integrity of both top and bottom remaining bars.
 - Upgraded strand insulation and optimized losses should be part of future rewinds
- Side ripple filler discoveries present risk for ground wall insulation failure of untouched stator slots.





Known 324 Stator Issue Review

- End Winding Material Concern – Dry Tie Replacement – TIL 1764
- End Winding – Looseness, Resonance, Component Cracking, & Failure
 - TIL's – 1965, 1966, & 2417
- Core Compression Band Looseness, Cracking, & Key Bar Rattle
- Core Compression, Looseness, Lamination Movement & Fracture
- Slot Ripple Filler - Bar Abrasion
- Bar – Strand Insulation Failure



Known 324 Rotor Issue Review

- Rotor Forging Dovetail Cracking (TIL 1292)
- Rotor Amortisseur Migration
- Rotor Radial Lead Cracking & Failure
- Rotor Turn Insulation Migration



IRMC 2024

Renaissance Las Vegas , NV

June 17-20, 2024

324 Generator Failure Discoveries, Concerns, & Repair

QUESTIONS

W. Howard Moudy

Director of Operations

National Electric Coil

hmoudy@national-electric-coil.com

724-787-4967

[*www.National-Electric-Coil.com*](http://www.National-Electric-Coil.com)

